Installing XL Imaging 32 bit Camera Driver on 32 bit Windows 10

1. Plug your camera into a USB 2 port on your PC.
2. Open Windows Device Manager.
3. Under 'Other Devices', locate the entry for 'USB 2.0 PC Camera'.
4. Right click on it and choose 'Update Driver' from the context menu.
5. Select the option: 'Browse My Computer for driver software'.
6. Click the 'Browse' button and navigate to the 'XL Imaging 32 bit' folder.
7. Click the 'Next' button.
8. You will receive a warning, 'Windows can't verify the publisher of this driver software'. This is displayed because the driver isn't code signed.
9. Choose the option to 'Install this software anyway'.
10. Windows will install the driver, and notify you when installation is complete.

You should now see a new Device Manager entry for the camera under 'Imaging Devices'.